

TABLA DE CONVERSIÓN DE CALIBRES G A MM

GAUGE	MM
8	4
10	3.5
11	3
12	2.8
13	2.4
14	2/2.1
15	1.8
16	1.6
17	1.4/1.5
18	1.2/1.3
19	1/1.1
20	0.9
21	0.8
22	0.7
23	0.6
24	0.55
25	0.5
26	0.45
27	0.4
28	0.35
30	0.3

Fuente: Atlas of Retinal and Vitreous Surgery; Travis A. Meredith; 1999, Mosby.